



Midwest Built. Midwest Tough. Guaranteed for Life.

Triple Pane Insulated Glass

Stay ahead of ENERGY STAR changes by offering your customers a more energy efficient glass option.



Reduces condensation & frost in winter by keeping interior pane warmer
Minimizes unwanted outdoor noise
20-year warranty, includes labor

1" oa. for DH, DS & PD
1 5/16" oa. for Euro Series
1 3/8" oa. for CW, AW, PW

Home Buyer Demand For Energy Codes: Results from Three Consumer Surveys

NAHB

9 out of 10 buyers would choose a highly energy efficient home with lower utility bills rather than one costing 2-3% less without those features
84% of home buyers believe that low utility costs are important when buying their next home
More than two thirds of buyers want ENERGY STAR rated windows, triple pane insulating glass and Lo-E insulating glass

Building Codes Assistance Project

83% of respondents believe that energy efficient homes have a higher resale value
79% would rather pay slightly more for a new home and have affordable, predictable operating costs and energy bills
77% disagree when a builder says new home amenities have to be sacrificed in exchange for energy code compliance

UND 2015 Public Opinion Survey

Nearly nine out of ten respondents (87%) support implementation of stronger energy efficiency requirements for new residential and commercial property construction in North Dakota
97% believe that energy efficiency is important to them

For a more in-depth summary of these surveys, visit <http://energycodesocean.org/consumers-take-action>



Energy Star is implementing stricter rules for windows, doors and skylights beginning in 2016. Minnkota Windows is ahead of the game and triple pane glass greatly exceeds requirements for energy efficiency under new guidelines set forth by the Dept. of Energy.

Accidental Glass Breakage Warranty: If a panel of glass installed into one of our windows should break during the glass warranty period, Minnkota will furnish a replacement at no charge. It's limited to the furnishing of a replacement IG and does not cover or include any labor costs incurred in removal or reinstallation of the IG. Shipping and handling are not covered by this warranty and are the responsibility of the original homeowner.